Montana Board of Oil and Gas Conservation **Environmental Assessment**

Operator: Devon Energy Production Company, L.P.
Well Name/Number: Crowe-DIR 15-16
Location: NW SE Section 15 T31N R15E
County: Hill , MT; Field (or Wildcat) Tiger Ridge
Air Quality
(possible concerns)
Long drilling time: No, 3 to 4 days drilling time.
Unusually deep drilling (high horsepower rig): No, small single derrick drilling rig to drill to 2500' TVD/2750'TMD.
Possible H2S gas production: No H2S gas, formation at TD.
In/near Class I air quality area: No, Class I air quality area.
Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required under 75-2-
211.
Mitigation:
_X Air quality permit (AQB review)
Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
Other:
Comments: No special concerns – using small rig to drill to 2500' TVD/2750'TMD.
Water Quality
(possible concerns)
Salt/oil based mud: No, freshwater, and freshwater mud system to be used only.
High water table: No high water table anticipated in this area.
Surface drainage leads to live water: No, closest drainages are unnamed ephemeral tributary drainages to
Beaver Creek, about 1/32 of a mile to the south and 1/16 of a mile to the north from this location.
Water well contamination: None, closest water well is about 1 mile and further in any direction from this
wellsite. Surface hole will be drilled with freshwater and freshwater mud, steel surface casing will be set
to 150' and cemented to surface from 150'. If productive 4 1/2" casing will be run and cemented to
surface to protect ground waters.
Porous/permeable soils: No, sandy bentonitic soils.
Class I stream drainage: Class I stream drainage is Beaver Creek.
Mitigation:
Lined reserve pit
\overline{X} Adequate surface casing
Berms/dykes, re-routed drainage
Closed mud system
Off-site disposal of solids/liquids (in approved facility)
Other:
Comments: 150' surface casing well below freshwater zones in nearby water wells. If productive
4 ½" casing will be cemented to surface. Adequate surface casing and operational BOP equipment will be
set and used.
Soils/Vegetation/Land Use

(possible concerns)

Steam crossings: No stream crossings required, only crossing ephemeral drainages.

High erosion potential: No, moderate cut, up to 11.0' and moderate fill, up to 12.0', required.

Loss of soil productivity: None, location to be restored after drilling well, if nonproductive. If productive
unused portion of drillsite will be reclaimed.
Unusually large wellsite: No, small well site 250'X215'.
Damage to improvements: Slight, surface use appears to be grassland adjacent to a cultivated field.
Conflict with existing land use/values: <u>Slight.</u>
Mitigation
Avoid improvements (topographic tolerance)
Exception location requested
X Stockpile topsoil
Stream Crossing Permit (other agency review)
X Reclaim unused part of wellsite if productive
Special construction methods to enhance reclamation
Other
Comments: Access will be from existing county gravel road and existing ranch trails. About 3/8 of a
mile of new access will be built to access this location from an existing ranch trail. Drilling fluids will be
freshwater and freshwater mud system. Cutting will be buried in the unlined pits. Drilling fluids will be
offsite disposed of in a stock pond for sealant, with surface owner approval. Pits will be allowed to dry
before being backfilled. No special concerns.
outside soming sweetings.
Health Hazards/Noise
(possible concerns)
Proximity to public facilities/residences: Closest residence is about 1/2 mile to the southeast from this
drilling location.
Possibility of H2S: None anticipated.
Size of rig/length of drilling time: Small single derrick drilling rig. Short drilling time 3 to 4 days drilling
Mitigation:
X Proper BOP equipment
Topographic sound barriers
H2S contingency and/or evacuation plan
Special equipment/procedures requirements
Other:
Comments: Adequate surface casing cemented to surface with working BOP stack should
mitigate any problems.
intigate any problems.
Wildlife/recreation
(possible concerns)
Proximity to sensitive wildlife areas (DFWP identified): None identified.
Proximity to recreation sites: None identified.
Creation of new access to wildlife habitat: No
Conflict with game range/refuge management: No
Threatened or endangered Species: Black-footed Ferret (Listed in Hill County by US Fish & Wildlife
website). Candidate species listed is the Greater Sage Grouse.
website). Candidate species listed is the Greater Sage Grouse.
Mitigation:
<u> </u>
Avoidance (topographic tolerance/exception)
Other agency review (DFWP, federal agencies, DSL)
Fencing of pits, drillsite
Other:
Comments: Surface is private grassland adjacent to a cultivated field. Ms. Windy Davis
indicated no Greater Sage Grouse in the Hill County area. No concerns.
TI: 4 - 2 - 1/C 1/ 1/D 1 4 - 1 - 2 - 1
Historical/Cultural/Paleontological

2

(possible concerns)

Proximity to known sites None identified
Mitigation
avoidance (topographic tolerance, location exception)
other agency review (SHPO, DSL, federal agencies) Other:
Comments: Surface is private grassland. No concerns.
Social/Economic
(possible concerns)
Substantial effect on tax base
Create demand for new governmental services
Population increase or relocation
Comments: No concerns at this time, development well within the Tiger Ridge Gas Field delineation.
Remarks or Special Concerns for this site
- -
Well is a 2500' TVD/2750'TMD. Eagle Formation test northwest side of Bear Paw Mountains.
Summary: Evaluation of Impacts and Cumulative effects
No long term impacts expected. Some short term impacts will occur, but can be mitigated in a short
<u>time.</u>
I conclude that the approval of the subject Notice of Intent to Drill (does/ <u>does not</u>) constitute a major action of state government significantly affecting the quality of the human environment, and (does/ <u>does not</u>) require the preparation of an environmental impact statement.
Prepared by (BOGC): \s\ Steven Sasaki
(title:) Chief Field Inspector
Date: August 30, 2010
Other Persons Contacted:
Montana Bureau of Mines and Geology, Groundwater Information Center website
(Name and Agency)
_Hill County water wells
(subject discussed)
_August 30, 2010
(date)
US Fish and Wildlife, Region 6 website
(Name and Agency)
ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA
COUNTIES, Hill County
(subject discussed)
June 9, 2010
(date)
Ms. Windy Davis, Montana FWP
(Name and Agency)

Greater Sage Grouse Leks in Hill County, Montana an E-Mail concerning Hegle 22-7 location in
Section 22 T31N R15E, Hill County, MT
(subject discussed)
June 9, 2010
(date)
If location was inspected before permit approval:
Inspection date:
Inspector:
Others present during inspection: